	Туре	L i	Hits	Search Text	DBs	Time Stamp	Comment
1	BRS	L1	2536	component and stress and test adj (piece artical member)	USPA T; US-P GPUB ; DERW ENT	2004/06/2 3 11:24	
2	BRS	L2	589	1 and (measur\$3 detect\$3 sens\$3 determin\$3) near3 propert\$3	USPA T; US-P GPUB ; DERW ENT	2004/06/2 3 11:50	
3	IS&R	L3	4	(("5127271") or ("5069417") or ("4934199") or ("4680897")).PN.	USPA T	2004/06/2 3 15:04	
4	BRS	L4	445	73/760	USPA T	2004/06/2 3 11:53	
5	BRS	L5	442	73/781	USPA T	2004/06/2 3 12:07	
6	BRS	L6	58	5 and specimen	USPA T	2004/06/2 3 11:59	
7	BRS	L7	327	73/788	USPA T	2004/06/2 3 12:13	
8	BRS	L8	9		USPA T; US-P GPUB ; DERW ENT	2004/06/2 3 12:14	
9	BRS	L9	68272 12	fill\$4 near5 (hollow bore cavity gap apperture) near stress a	USPA T	2004/06/2 3 15:05	
10	BRS	L10	22	fill\$4 near5 (hollow bore cavity gap apperture) near stress	USPA T	2004/06/2 3 15:05	

	Error Definition	Er ro rs
1		0
2		0
3		0
4		0
5		0
6		0
7		0
8		0
9		0
10		0